Field Inspection Details

Number of Trees	Any Other Information	Name
0		Nagabhushan G
Date of Inspection	**Remarks**	
27/09/2016		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	27/09/2016	27/10/2016	COMPLETED
EE	MALTHESH	27/09/2016	27/10/2016	COMPLETED
AEE	JAYALINGAPPA B L	27/09/2016	27/10/2016	COMPLETED
AE	NAGABHUSHAN G	27/09/2016	27/10/2016	COMPLETED
AE	NAGABHUSHAN G	27/09/2016	27/10/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0169, W0173, W0186, W0213, W0171, W

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾ[illegible]